

MFC-3820CN Supported PC Software Functions

Computer Platform & Operating System		Software Functions	PC Interface
Windows®	98, 98SE	Printing, PC Fax ³ , Scanning	USB
	Me	Printing, PC Fax ³ , Scanning	USB
	2000 Professional	Printing, PC Fax ³ , Scanning	USB
	XP	Printing, PC Fax ³ , Scanning ⁴	USB
Mac® Operating Systems	OS 8.6 - 9.2	Printing, PC Fax, Scanning ⁵	USB ⁷
	OS X v. 10/10.1 or greater	Printing, PC Fax, Scanning ^{5,6}	USB ⁷

Windows® 95 or Windows NT® 4.0 do not support USB.

For the latest drivers, access the Brother Solutions Center at <http://solutions.brother.com>. All software supplied only on CD.

^q : Up to 4800x1200 optimized dpi color output achievable using Photo mode when printing on high quality photo paper. (See User's Guide for details.)

* : Based on Brother #1 chart with MMR Coding System and Standard Resolution.

^ : SMTP/POP3 mail server support and account required.

1 : Requires additional purchase.

2 : Standard Resolution.

3 : Brother PC Fax send only for Network users.

4 : Maximum Scanning resolution with Windows® XP is limited to 1200 x1200 dpi (resolutions up to 2400 dpi can be selected using the Brother Scanner Utility).

5 : Dedicated "Scan" key and Direct Network Scanning not supported in Mac® Operating Systems.

6 : Scanning only available for Mac® OS 10.2.1 or greater.

7 : Third party USB ports are not supported.

MFC-3820CN Minimum System Requirements

Computer Platform & Operating System		Processor Speed	Minimum RAM	Recommended RAM	Available Hard Disk Space (For Drivers)
Windows®	98, 98SE	Pentium 75MHz	24MB	32MB	160MB
	Me	Pentium 150MHz	32MB	64MB	160MB
	2000 Professional	Pentium 133MHz	64MB	128MB	160MB
	XP	Pentium 233MHz	64MB	128MB	160MB
Mac® Operating Systems	OS 8.6 - 9.2	All base models meet minimum requirements	32MB	64MB	80MB
	OS X v. 10/10.1 or greater	All base models meet minimum requirements	128MB	160MB	80MB